
TOPIC Mahlwinkel 25X1X	Airfield				
EVALUATION	PLACE OF	BTAINED		25	5X1C
DATE OF CONTENT 10					
DATE OBTAINED	25X1	DATE PREPARE	D 16 Decemb	er 1952	-
REFERENCES					
PAGES ENC	LOSURES (NO. & TYPE)	l - ske	tch on ditto		and the second section of the section o
REMARKS					
				J. 11-5	
X .				 	

- Source made photographs of a portion of the construction plan for Mahlwinkel airfield. The photographs show temporary buildings, construction sheds and power lines.
- 2. The Soviet construction headquarters in worder which was designated Teresh-chenko informed the Bauunion in Brandenburg that all construction machines and construction workers were to be withdrawn from Hahlwinkel airfield by 15 December 1952. Source believed that construction work at the field could be completed by this date. On 10 November, a total of 226 men were employed at the field. Construction work was supervised by Paul Klingeberg who was scheduled to supervise construction work at Parchim airfield after completion of the installation in Mahlwinkel.
- 3. The landing strip was covered with an 8-cm layer of small cinders and the remainder of the airfield area was covered with a 5 cm layer of cinders. Since considerable difficulties were experienced with this earth obtained at Tangerhuette, the Bauunion in Brandenburg submitted plans for the construction of a concrete runway to the construction headquarters in erder. However, these plans were not approved. The Bauunion in Brandenburg ordered seeding tests to be made with this earth. Then a large amount of water was applied to the earth, the grass seeds sprouted; when medium amounts of water were added, the sprouted grass turned yellow, withering completely when the earth was dry. Although the Bauunion Brandenburg considered these tests as unsatisfactory, the Russians were satisfied with them. Source did not know whether the Sowiet construction headquarters intended to have a temporary runway of piewced steel planks constructed at the field. Trees within the approach lanes were cut, but otherwise these approach lanes were not being worked on in any other way.

CLASSIFICATION	SECRE
----------------	-------

			Approved For Release 2003/02/27 : CIA-RDP82-00457R016100230 606²6 ¹ A					
25X1A		1.	Correct. The photo raphs made by source were not suitable for reproduction. For this reason, a dicto was made on the basis of the information furnished by source. For ditto, see Annex. For places and roads shown on the ditto, see	/1				
25X1A		2.	Comment. It has been determined that no runway will be built at the field. It remains to be seen whether the landing field will meet requirements.	X I				



Approved For Release 2003/02/27: CIA-RDP82-00457R016100230006-6